

Repairs to Minor and Major Tanks in Channarayapatna Taluk.

Q.—118. Sri N. G. NARASIMHE GOWDA (Sravanabelagola).—

Will the Government be pleased to state:—

(a) the number of minor and major tanks in Channarayapatna Taluk;

(b) the number and names of such tanks which have been so far repaired;

(c) the number and names of such of them which are yet to be repaired; (hobliwise information to be furnished)

(d) the number of applications received from ryots for repairing tanks

and the stage at which these applications are pending (hobliwise information to be furnished);

(e) whether and if so when do they propose to undertake repairs to the tanks which are yet to be repaired?

A.—Sri H. K. VEERANNA GOWDH (Minister for Public Works).—

(a) Major Tanks ... 45
Minor Tanks ... 209

(b) *Vide* List 'A' appended.

(c) *Vide* List 'B' appended.

(d) *Vide* statement 'C' appended.

(e) These works will be taken up according to requirements and subject to availability of funds.

List 'A' showing the names and number of tanks which have so far been repaired.

Sl.
No.

Name of Tanks repaired.

- 1 Dindagoor Tank.
- 2 Anekere Chikkere Tank.
- 3 Marenahally Tank (Only Minor Rpair
- 4 Nettekere Tank.
- 5 Cholambally Tank.
- 6 Bookanabetta Tank.
- 7 Yachanagatta Tank.
- 8 Didega Tank.
- 9 Metikere Tank
- 10 Modalagere Tank.
- 11 Govarahosully Tank.
- 12 Margur Shevara Tank.
- 13 Kumbarahally Tank.
- 14 Kurdahally Tank.
- 15 Hongehally Tank.
- 16 Byladaber Tank.
- 17 Hebalalu Tank.
- 18 Dasaparanaikanakatte.
- 19 Kalkane Amanikere.
- 20 Naggehalli Hirekere.
- 21 Baddikere Tank.
- 22 Mavinahally Juranekatte.
- 23 Madalagur Tank.
- 24 Dasapura Tank.
- 25 Yachanagatta Tank.
- 26 Nuggehally Harakatte.
- 27 Santhe Sivana Tank.
- 28 Kaggere Mathikere Tank.
- 29 Madihally Seggekatte.

Sl. No.	Name of Tanks repaired
30	Keggere Iyanakere Tank (Only minor repairs)
31	Ungaragere Gowdanakatte.
32	Gowdanakatte of Belegehally.
33	Dadigatta Tank.
34	Hosahally Tank.
35	Sundehally Tank.
36	Doddare Tank.
37	Sungahally Tank.

List 'B' showing the number and names of tanks which are yet to be repaired.

Hiresave Hobli.

- 1 Repairs to Thotikere.
- 2 Repairs to Metikere.
- 3 Repairs to Waste Weir of Hiresave Tank.
- 4 Repairs to Waste Weir of Mathigatta Tank.
- 5 Restoring Madihally Kempagakatte.
- 6 Earth work maintenance to Balaganetic Tank.

Nuggehalli Hobli.

- 7 Restoring Muddainnakalle in Dodere kaval.
- 8 Maintenance to feeder channel to Nuggehalli Hirekere.
- 9 Restoring Venkammiachan katte.
- 10 Do Hulikere Boranakatte.
- 11 Repairs to leaky sluice to Honnammonakere.
- 12 Restoring Narasimpuradakatte.
- 13 Repairs to Sluice of Thavarakere.
- 14 Do Jamboor Hirekatte.
- 15 Do Jamboor Amanikere.

Bajur Hobli.

- 16 Repairs to Kambal Muthinakatte.
- 17 Constructing pipe sluice to Kambal Mathenakatte Tank.
- 18 Do Waste Weir and breach filling Do
- 19 Do Waste Weir of Kambal Hirekere.
- 20 Repairs to Govenkere sluice.
- 21 Do Byadarahally Tank sluice.
- 22 Do Banavase Tank.
- 23 Do Chamarajapura Tank sluice.
- 24 Restoring Baligatte Tank.
- 25 Do Hodekekatte.
- 26 Do Ingalamakarakere.

Kasaba Hobli.

- 27 Improvements to Amanikere of Channarayapatna.
- 28 Constructing Acqueduct to Janevara Tank.
- 29 Repairs to Bediganahally Tank.
- 30 Restoring Nagasamudra Tank.
- 31 Repairs to Kabasinda Tank.
- 32 Restoring Yeliyur major Tank.
- 33 Do Narenahally Tank.

(SRI H. K. VEERANNA GOWDH)

Sravanabelagola Hobli.

- 34 Restoring Majjenahally Tank.
- 35 Repairs to Bekka Amanikere.
- 36 Maintenance to Rachenhalla Tank.
- 37 Constructing sluice to Daidgatta Tank.
- 38 Repairs to Sundahally Tank.
- 39 Restoring Kabbalu Breached Tank.
- 40 Restoring Iadigatta Tank.
- 41 Constructing sluice to Tinantasapura Tank.
- 42 Strengthening the bund of Bekka Amanikere.
- 43 Do to Kothanagatta Tank.
- 44 Do to Paramadkere.
- 45 Improvements to Pandethankalle.
- 46 Repairs to Ganjekatte Tank.
- 47 Do Kanderi Tank.
- 48 Halebelgola Tank.

Dandiganahally Hobli.

- 49 Restoring Chikkade Brahe Devarakere.
- 50 Urgent repairs to Jerumalapura Tank.
- 51 Constructing sluice and waste weir to Doddamathegatta Tank.
- 52 Do do Nettikere.
- 53 Repairs to Kundur Tank.
- 54 Do Vagarehally Tank.

List 'C' Statement of applications received from Ryots and Stage of Pendency.

Sl. No.	Petition by whom	Subject	Hobli	Stage of Pendency
1	Villagers of Harosomanahally.	Restoration of Harosomanahally Tank	Nuggehalli	Ordered to be dropped.
2	Residents of Muttagada Honnenahally and Kaggeri Nuggehalli.	Repairs to Dyavanakere	Do	Executive Engineer's report is called for.
3	Residents of Agrahara Belagoli.	Repairs to Honnamanakere and restoration of Hosakere.	Do	Repairs to Honnamanakere is in progress and restoration of Hosakere is under investigation.
4	Do of Mullikere	Restoration of Mullikere tank.	Do	Under investigation.
5	Ryots of Nuggehalli Village	Restoration of Feeder channel Nuggehalli Hirekere.	Do	This has to be surveyed.
6	Villagers of Jambur	Repairs to Jamburkere katte	Do	Estimate is under preparation.
7	Moothuga Honnanahally	Maintenance work of Moothuga Honnanahalli Tank.	Do	Surveyed and estimate is under preparation.
8	Villagers of Kaggere	Repairs to Kaggere Iyanakere	Do	Estimate is under preparation (for restoration of tank).
9	Sri B.N. Boriah, Belegole	Lowering the sluice level of Muddanahnakatte.	Do	Orders passed to the effect that there is no need for lowering this sluice level.
10	Villagers of Hosur Kaval	Breach filling work of tank	Do	Under investigation.
11	Do of Belagola Agrahara.	Closing the leakage of sluice of Honnamanakere.	Do	Estimate has been got up and is under sanction.
12	N. N. Krishna Murthy, Shanbhog.	For entrusting some work to him	Do	Under consideration.
13	Sri N. G. Narasimha Gowda, Nuggehalli.	Construction of a feeder channel to Tavarekere Tank.	Do	Project ordered to be dropped as it involves acquisition of valuable lands at very heavy cost.
14	Atchakatdars, under Nanjanakere of Adagurama Chapparadahalli, Honnanahalli.	Restoration of Nanjanakere	Hirisave	Under restoration.

Sl. No.	Petition by whom	Subject	Hobli	Stage of Pendancy
15	Villagers of Kalenahalli	Silt clearing the channel of Channarayapatna Amanikere.	Channarayapatna (Kasaba).	The work being attended to.
16	Atchkatdars under Oorumundinakere of Maranahalli.	Restoration of Oorumundinakere	Do	Mutchalika has been obtained.
17	Ryots of Barlu.	Repairs to Ane near Barlu	Do	Estimate is under preparation.
18	Ryots of Chamadahalli	Construction of Ane in place of old one	Do	To be investigated.
19	Sri B. L. Thimme Gowda, V. P. Chairman of Bommanahalli.	Repairs to the village tank	Shravaanabelagola	The estimate is under preparation.
20	Villagers of Kumbenahalli	Repairs to sluice and Waste-weir of the village tank.	Do	The estimate has been got up and is under sanction.
21	Do Madene Village	Repairs to the village tank	Do	Do
22	Do Chalya	Repairs to sluice of Hirekere	Do	do
23	Do Biranahalli	Do to village tank	Do	do
24	Hulgikere villagers	Repairs to waste-weir of their tank	Do	The estimate is under preparation.
25	Villagers of Aruvanahalli	Repairs to tank.	Do	The estimate has been got up and is under sanction.
26	Villagers of Marisettihalli	Repairs to sluice	Do	Do
27	Sri G. P. Padmiah	Construction of sluice to Janathapurada tank.	Do	The estimate is under preparation.
28	Ryots of Thimmalapura	Repairs to the bund of the village	Dandiganahalli	The estimate has been got up and is under sanction.
29	Ryots of Doddas Karadi	Restoring the tank	Do	The estimate is under preparation.
30	Ryots of Sagatavalli	Repairs to sluice and protecting tank	Do	The estimate has been got up and is under sanction.
31	Ryots of Muddanahalli	Constructing a tank above the deviation road.	Do	The project is considered not feasible.
32	Ryots of Thippur	New sluice and waste-weir to the tank	Do	The estimate is under preparation.
33	Ryots of Somanathahalli	Repairs to W.W. of Oorumundinakere.	Do	Estimate has been got up for sanction.
34	Ryots of Chamarajapura	Repairs to village tank.	Bagur	The estimate is under preparation
35	Ryots of Govinakere	Restoration of tank	Do	Do